



FIG. 1



Pulsed artery

FIG. 2A


Before autofluorescence correction
(2 hrs. after excision)



Non-pulsed artery

FIG. 2B

Before autofluorescence correction
(2 hrs. after excision)




R1L1 : Heparin, no pulse
(left artery)
8 hrs.

FIG. 3A




R1R1 : Heparin, with pulse
(right artery)
8 hrs.

FIG. 3B



R2L1 : Heparin, with pulse
(left artery)
5 hrs.


FIG. 3C



R2R1 : Heparin, no pulse
(right artery)
5 hrs.


FIG. 3D

104721 16502007



4R2: Heparin, no pulse (right artery)


FIG. 4B



1L3: Heparin, no pulse (left artery)


FIG. 4D

5/9



12R1: Heparin, with pulse (right artery)

FIG. 5A



12L1: Heparin, no pulse (left artery)

FIG. 5B

40033 144
T04T3T T650300T




FIG. 6




FIG. 7




FIG. 8A

9/9



FIG. 8B




FIG. 8C

44737 45000